

May 8 2018 ~~2014~~ Doyle, CA

- Differential Speed limit
 - Historic reduction of passing lanes
- Primarily about **two** lanes for safety reasons
 - Places for snow storage
- Immediate safety measures
 - * Warning lights from depot
 - * High wind advisory protocols
 - * Lack of wind & snow warning signs on 395
 - * Improve striping & spot turning lanes
 - * Lack of ability for emergency vehicles to pass
 - * Upgrading fencing for deer/cattle